OLD TRAILS DEMOLITION P.O. BOX 3847 KINGMAN, AZ 86402 (928) 753-2957 FAX (928) 753-5533

#### ASBESTOS TESTING REPORT

FOR:

CITY OF KINGMAN ATTENTION: JIM MCERLEAN 410 PARK STREET - REAR HOUSE KINGMAN, AZ

REPORT DATE: NOVEMBER 25, 2015

#### TABLE OF CONTENTS

I.	Scope of Work Page 4					
II.	Building Description Page 4					
III.	Inspection Methods Page 4					
IV.	Laboratory Analytical Method Page 4					
V.	Results of Investigation Page 5					
VI.	Notes from Inspector Page 5					
	List of Tables					
-1.	Asbestos Results Page 6					
Appendix A - Laboratory Analytical Report & Chain Of Custody Appendix B - Certification						

#### OLD TRAILS DEMOLITION P.O. BOX 3847 KINGMAN, AZ 86402 (928) 753-2957 FAX (928) 753-5533

November 25, 2015

City of Kingman 310 N. 4th Street Kingman, AZ 86401

Dear Jim McErlean:

Upon your request, on November 16th, Old Trails performed a thorough inspection of suspect ACM's for areas where renovation or demolition is to be performed. Please see attached report for the results.

Should you have any questions on the findings or recommendations of this report, feel free to contact Rob Lackey, Certified AHERA Building Inspector at Old Trails Demolitions at (928) 753-2957.

Sincerely

**Rob Lackey** 

AHERA Building Inspector #G2614

#### I. Scope of Work

Old Trails was hired to perform an asbestos inspection for City of Kingman at 410 Park Street - Rear House, Kingman, AZ. We performed inspection and bulk sampling on November 16th, 2015 per information provided by Jim McErlean.

The purpose of asbestos inspection was to ascertain the presence of asbestos or to prove materials being disturbed in project are negative for asbestos prior to renovation or demolition. If any suspect material is found that was not listed, please contact us for further testing.

#### II. Building Description

The property tested is a single story residential house.

#### III. Inspection Methods

A total of thirteen (13) bulk samples were collected in various areas of the single story residental house. A identification number was used for each sample. A total of 13 samples were analyzed (including all layers), results are reported and can be found attached in Appendix A.

#### IV. Laboratory Analytical Method

The bulk samples were submitted to LA Testing, to be analyzed for asbestos content by Polarized Light Microscopy using the EPA method 600/R-93/116. LA Testing is accredited under the NIST/NVLAP program for asbestos in bulk material.

To ensure valid and reliable results and to monitor samples during collection, shipment, testing and subsequent disposal phase of potentially asbestoscontaining materials, Old Trails, has established a quality assurance program for the collection and submittal of bulk samples. This program consists of:

- Creation of chain of custody form to keep track of the samples always by assigning responsibility for each phase of the data collection and analysis process to a specific person.

- Use of EPA-accredited laboratories that participate in the National Voluntary Laboratory Accreditation Program (NVLAP) sponsored by to National Institute of Standards and Technology for asbestos testing.

#### V. Results of Investigation

In accordance with the Environmental Protection Agency (EPA), any construction material containing more than one percent asbestos by weight is considered an Asbestos Containing Material (ACM). In addition, according to policies developed for schools, by the EPA, a homogenous material is considered to contain asbestos, when asbestos is detected in one or more samples of the subject material.

Table 1 - summarizes the homogenous areas inspected and sampled and presents the laboratory results.

Notes from inspector:

In conclusion, all twenty samples came back negative for asbestos.

Sincerely

Rob Lackey

**AHERA Building Inspector** 

				TABLE 1			
				ASBESTOS RESULTS	RESULTS		The same of the sa
				410 PARK ST	410 PARK STREET - REAR HOUSE	OUSE	
Area Tested	Type of Material Sample #	Sample #	Locations	Quantity	Condition	PLM Results	Percent
Exterior	Stucco	1-1	Stucco	NA	Good	Q.	%0
Exterior	Stucco	1-2	Strcco	N/A	Good	Q	%0
Exterior	Stucco	1-3	Stucco	NA	Good	N	%0
Exterior	Roof	2-1	Roof	N/A	Good	QN	%0
Exterior	Roof	2-2	Roof	N/A	Good	ND	%0
Exterior	Roof	2-3	Roof	N/A	Good	Q	%0
Interior	Drywall	3-1	NE Room	N/A	Good	N	%0
Interior	Drywali	3-2	Back Far East	NA	Good	N	%0
Interior	Drywall	3-3	Back Far West	N/A	Good	Q	%0
Interior	Tile	4 - 1	Tile	N/A	Good	Q	%0
Interior	Tile	4-2	Tile	N/A	Good	Q	%0
Interior	Grout	5-1	Grout	N/A	Good	2	%0
Interior	Grout	5-2	Grout	N/A	Good	ND	%0

## APPENDIX A LABORATORY ANALYTICAL REPORT & CHAIN OF CUSTODY



#### **LA Testing**

82 West Sierra Madre Boulevard Sierra Madre, CA 91

Tel/Fax: (626) 355-4711 / (626) 355-4497

http://www.LATesting.com/sierramadrelab@latesting.co

LA Testing Order: 451500818 Customer ID: OTRL42

Customer PO: Project ID:

Attention: Rob Lackey

Old Trails

301 S. 4th Street Kingman, AZ 86401 Phone: (928) 753-2957

Fax:

Received Date: 11/19/2015 12:00 PM

**Analysis Date**: 11/24/2015 **Collected Date**: 11/16/2015

Project: 410 Park Street - Rear House

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Asbestos		
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
1-1	Stucco - N/A	Gray/White Non-Fibrous		100% Non-fibrous (Other)	None Detected
151500818-0001		Homogeneous			\$**
1-2	Stucco - N/A	Gray/White Non-Fibrous		100% Non-fibrous (Other)	None Detected
151500818-0002		Homogeneous			
1-3	Stucco - N/A	Gray/White Non-Fibrous		100% Non-fibrous (Other)	None Detected
151500818-0003		Homogeneous			·
2-1	Roof - N/A	White/Black Fibrous	20% Cellulose 20% Glass	60% Non-fibrous (Other)	None Detected
151500818-0004		Heterogeneous			
?-2	Roof - N/A	White/Black Fibrous	20% Celiulose 20% Glass	60% Non-fibrous (Other)	None Detected
151500818-0005		Heterogeneous			
2-3	Roof - N/A	Gray/White Fibrous	20% Cellulose 20% Glass	60% Non-fibrous (Other)	None Detected
151500818-0006		Heterogeneous			
3-1	Drywall - NE room	White/Pink Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
51500818-0007		Homogeneous			
3-2	Drywali - Back far east	White Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
51500818-0008		Homogeneous			
3-3	Drywall - Back far west	White Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
151500818-0009	······	Homogeneous			
1-1	Tile - N/A	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
151500818-0010		Homogeneous	<del></del>		
1-2	Tile - N/A	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
51500818-0011		Homogeneous			
5-1	Grout - N/A	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
51500818-0012		Homogeneous			
5-2	Grout - N/A	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
51500818-0013		Homogeneous			

Initial Report From: 11/24/2015 17:22:26

PLM - 1.65 Printed: 11/24/2015 2:22 PM

Page 1 of 2



#### **LA Testing**

82 West Sierra Madre Boulevard Sierra Madre, CA 91

Tel/Fax: (626) 355-4711 / (626) 355-4497

http://www.LATesting.com / sierramadrelab@latesting.co

LA Testing Order: 451500818 Customer ID: OTRL42

> **Customer PO:** Project ID:

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Non-Asbestos <u>Asbestos</u> Sample Description Appearance % Fibrous % Non-Fibrous % Туре

Analyst(s)

Guillermo Hernandez (13)

Arturo Casas Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by LA Testing Sierra Madre, CA NVLAP Lab Code 102116-0, CA ELAP 1269

[ Initial Report From: 11/24/2015 17:22:26

OrderID: 451500818



### Asbestos Chain of Custody LA Testing Order Number (Lab Use Only): 4 5 1 5 0 0 8 1 8

LA TESTING

OZ VV. SIERRA MADRE
SIERRA MADRE, CA 91024
PHONE: (626) 355-4711
Fax: (626) 355-4497
e ☐ Different

Company : Old Troile			LA Testing-Bill to: ⊠ Same ☐ Different			
Company : Old Trails			If Bill to is Different note instructions in Comments**			
Street: 301 S. 4 <sup>th</sup> Street			Third Party Billing requires written authorization from third party			
City: Kingman State/Province: AZ		Province: AZ	Zip/Postal Code: 8640	)1 Cour	itry: USA	
Report To (Name): Rob Lackey			Fax #: 928-753-5533	****		
Telephone #: 928-753-2957			Email Address: oldtrails@npgcable.com			
Project Name/Number:		rect - Real		ns december transfered angued ang Pil Terretoparageastari. Protop gress tabun at		
Please Provide Result				S. State Samples Take	en:	
			Qptions* – Please Che			
For TEM Air 3 hours throug	h 6 hours, please call ahea	nd to schedule.*There is a	72 Hour Description of the state of the stat	96 Hour 1 Week TEM AHERA or EPA Level II and Conditions located in the	TAT. You will be asked	
PCM - Air	E-re-		ihr TAT (AHERA only)	TEM- Dust		
☐ NIOSH 7400		☐ AHERA 40 CF	R, Part 763	☐ Microvac - ASTM	D 5755	
w/ OSHA 8hr. TWA		☐ NIOSH 7402		☐ Wipe - ASTM D64	80	
PLM - Bulk (reporting limit)		☐ EPA Level II		Carpet Sonication	(EPA 600/J-93/167)	
PLM EPA 600/R-93/116 (<1%)		☐ ISO 10312		Soil/Rock/Vermiculi	Manager Special Control of the Contr	
PLM EPA NOB (<1%	'	TEM - Bulk			☐ PLM CARB 435 - A (0.25% sensitivity)	
Point Count		☐ TEM EPA NOB		☐ PLM CARB 435 - B (0.1% sensitivity)		
☐ 400 (<0.25%) ☐ 1000 (<0.1%)		NYS NOB 198.4 (non-friable-NY)		☐ TEM CARB 435 - B (0.1% sensitivity)		
Point Count w/Gravimetric		☐ Chatfield SOP		☐ TEM CARB 435 - C (0.01% sensitivity)		
☐ 400 (<0.25%) ☐ 1000 (<0.1%)		☐ TEM Mass Analysis-EPA 600 sec. 2.5		☐ EPA Protocol (Semi-Quantitative)		
NYS 198.1 (friable in NY)		TEM - Water: EPA 100.2		☐ EPA Protocol (Quantitative)		
☐ NYS 198.6 NOB (non-friable-NY)		Fibers >10µm		Other:		
☐ NIOSH 9002 (<1%)		All Fiber Sizes  Waste  Drinking				
	☐ Check For P	ositive Stop - Cle	arly Identify Homog	enous Group		
eris vara vala eras vara sell var de Nape Herita va fil a file de Herita de						
Complere Name:			Samplers Signature:			
Samplers Name:						
Sample #		Sample Description		Volume/Area (Air) HA # (Bulk)	Date/Time Sampled	
		Sample Description				
Sample #				HA#(Bulk)	Sampled	
Sample #				HA#(Bulk)	Sampled 13	
Client Sample # (s): Relinquished (Client):	* Prease	See attact	red *	HA# (Bulk)  Total # of Samples:  Time	Sampled  13	
Client Sample # (s): Relinquished (Client): Received (Lab):	*Prease	su attach		HA# (Bulk)  Total # of Samples:	Sampled  13 : 12:00 PM	
Client Sample # (s): Relinquished (Client):	*Prease	See attact	red *	HA# (Bulk)  Total # of Samples:  Time	Sampled  13	

Page 1 of \_\_\_\_\_ pages

#### OrderID: 451500818 Request for Laboratory Services / Chain of Custody - Asbestos

			Carried and the contract of th	A TRACE TO BE A PROPERTY OF THE PARTY OF THE
	ob or Julie 1	Lackey		Hygeia Laboratories Inc
Company Name 0	ld Trails			801W - Sierra Madre Blvd Sierra Madre: CA 91024
Company Address p	.O. Box 3847			(629) 355-4713
City State Zip K	ingman, AZ 8	36402		(828) 355-4497 Fax (IIIIIIIIIIIIIII Www.hygeralaberatories.com
	928) 753-2957		) 753-5533	
	928) 716-6874			, geia Reference #
Client Project Name	110 Pak	Street-	Rea Hou	Z.Q
Client Project #		-		Samples Submitted 3
Purchase Order#				Samples Analyzed
Send Report Via [	Emai KK Fax	D v	erbal Resours?	Do you require a mailed report?
Committee And designation	ldtrails@npgc			co you require a mailed report?
			p-107-00	
umaround time	Normal (3-5 business of	tays) Ll Nex	t Day (24 hrs)	Same Day (Rush) U Weekend Rush
Type of Sample : Li			Liust (wipe)	Soir Paint Water Cher
Asbestos (Optical)	Asbestos (TE	EM)		
D RM	☐ AHERA		Qualitative Du	st Qualitative Bulk
FLM Point Count 400 pt	s DEPA Level	li	Quantitative D	Just Sem-Quantitative Bulk
FLM Point Count 1000 p			Drinkon Water	r (potable)
POM	D 50 10312		[] Drinking Water	
8				
			Partical Charac	sterization Supplies
Additional Instructions				
See Attached S	ample Log			
For Lab Use Only Sa	ample Integrity			
Results Reported By	imple integrity	accept	reject	1st Sample #
Date	Tima	In Differen		Price / Sample
)ate				
ate				Invoice #
ommenis	Time	muais	For the department of the section	Log Out Date
Reliquished By	Received By	. Date	Time	Pogeon for Chair
(Signature)	(Signature)		- 1 11112	Reason for Change of Custody
Rob Lang	- 10 = 1			
0	or an an or			
5.50	36			
e sample collector is responsible	e for ensuring that all same	olës have been pre	eserved according to	the appropriate and appplicable methodology.
			we work the fig to	
	**************************************			Hevised 12/1/2007

#### **OLD TRAILS**

#### SAMPLE LOG - 410 PARK STREET - REAR HOUSE

Collection: November 16, 2015

Collected by: Rob Lackey

- 1-1 = Stucco
- 1-2 = Stucco
- 1-3 = Stucco
- 2-1 = Roof
- 2-2 = Roof
- 2-3 = Roof
- 3-1 = Drywall NE Room
- 3-2 = Drywall Back Far East
- 3-3 = Drywall Back Far West
- 4-1 = Tile
- 4-2 = Tile
- 5-1 = Grout
- 5-2 = Grout

#### APPENDIX B LICENSING

(7)

# THE ASBESTOS INSTITUTE

Certifies that

# Robert Lackey

has attended the EPA approved course

AHERA Building Inspector Refresher

Approval Code: CA-089-06

January 9, 2015 and successfully passed the competency exam.

Date of Examination: 1/9/2015

Date of Expiration:

Approved Instructor

William T. Cavness Director

THE ASBESTOS INSTITUTE

20033 N. 19th Avenue Phoenix, AZ 85027 602-864-6564 Building #6